

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2N5038 (Cont'd) DE327 1 DGE SDT7603 1 SOD SDT7609 1 SOD 2N3448 3 MOTA 2N6338 3 MOTA BUX11N 3 SGSI	2N5053 (Cont'd) BY90 3 APX DE316 3 DGE 2N5054 2N6304 1 MOTA DE161 1 DGE SD1300 1 THCS A490 3 APX BFY90 3 APX DE316 3 DGE 2N5055 DE159 1 DGE 2N5056 2N4209 1 MOTA DE159 1 DGE PN3640 3 NSC 2N5057 2N4209 1 MOTA DE159 3 DGE PN3640 3 NSC 2N5058 2N3439 1 RCA D44T2 1 GESY DE154 1 DGE THC5058 1 SPR TP5058 1 SPR DE396 3 DGE 2N5059 2N3440 1 RCA D44T4 1 GESY DE154 1 DGE THC5059 1 SPR TP5059 1 SPR BD115 3 PHIN BPN18 3 SIEG BFN26 3 SIEG D44T2 3 GESY DE396 3 DGE TN3440 3 NSC 2N5066 DE123A 1 DGE 2N5067 2N5758 1 MOTA BDX91 1 PHIN D44VM4 1 GESY DE130 1 DGE 2N3442 3 RCA 2N4914 3 RCA 2N6262 3 RCA BDW21A 3 SGSI BDW51C 3 SGSI DE385 3 DGE 2N5068 2N5758 1 MOTA BDX91 1 PHIN D44VM7 1 GESY DE130 1 DGE 2N3442 3 RCA 2N4914 3 RCA 2N6262 3 RCA BDW21A 3 SGSI BDW51C 3 SGSI DE385 3 DGE 2N5069 2N5758 1 MOTA BDX93 1 PHIN D44VM10 1 GESY DE130 1 DGE THC5069 1 SPR 2N3442 3 RCA 2N4914 3 RCA 2N6262 3 RCA BDW21B 3 SGSI BDW51C 3 SGSI DE385 3 DGE 2N5070 BLX13 1 PHIN MRF426A 3 MOTA 2N5071 BLY93A 1 PHIN 2N3927 3 MOTA 2N5477 3 GSE 2N5643 3 THCS MRF314A 3 MOTA 2N5072 BLY90 1 PHIN 2N6084 3 THCS MRF240 3 MOTA 2N5073 DE154 1 DGE 2N5074 DE95 1 DGE 2N5075 DE95 1 DGE 2N5076 DE95 1 DGE 2N5077 2N4416 1 IFC 2N5397 1 INL DE452 1 DGE THJ5078 1 SPR TMPF5078 1 SPR TP5078 1 SPR	2N5078 (Cont'd) 2N5485 3 MOTA 2N5486 3 INL THJ4416 3 SPR THJ5397 3 SPR TMPF4416 3 SPR TMPF5397 3 SPR TP4416 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX 2N5079 D40D2 1 GESY 2N5080 D40D2 1 GESY DE123A 1 DGE 2N5081 DE123A 1 DGE 2N5082 DE123A 1 DGE 2N5083 2N5347 1 MOTA D44VM10 3 GESY 2N5084 2N5347 1 MOTA D44VM10 3 GESY 2N5085 2N5347 1 MOTA D44VM10 3 GESY 2N5086 BC557 1 PHIN BCX71C 1 SIEG BCX71D 1 SIEG BCY79 1 SGSI DE159 1 DGE PN200 1 NSC THC5086 1 SPR 2N2907A 3 PHIN BC478 3 SGSI BC850C 3 PHIN BC860A 3 PHIN BC875A 3 PHIN BCF29 3 APX BCF70 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN BCY70 3 PHIN BCY71 3 PHIN MMBT5086 3 MOTA THC557 3 SPR THC2604 3 SPR THC2605 3 SPR THC3962 3 SPR 2N5086-18 DE159 3 DGE THC4965 3 SPR 2N5087 BCX71C 1 SIEG BCX71D 1 SIEG BCY79 1 SGSI DE159 1 DGE PN200 1 NSC THC5087 1 SPR THC5087 1 SPR BC177 3 SGSI BC178 3 SGSI BC179 3 SGSI BC214L 3 SPR BC559 3 PHIN BC850C 3 PHIN BC860A 3 PHIN BCF30 3 APX BCF70 3 PHIN BCY71 3 PHIN MMBT5087 3 MOTA THC214 3 SPR THC3964 3 SPR THC3965 3 SPR 2N5088 BC547A 1 PHIN BCW60D 1 SIEG BCY59 1 SGSI DE123AP 1 DGE PN200 1 NSC THC5088 1 SPR TMPT5088 1 SPR BCF32 3 APX BCW71 3 PHIN MMBT5088 3 MOTA THBC547A 3 SPR 2N5089 BC549C 1 PHIN BCW60D 1 SIEG BCY59 1 SGSI DE123AP 1 DGE THC5089 1 SPR TMPT5089 1 SPR BC107 3 SGSI BC109 3 SGSI BC184L 3 SPR BC549 3 PHIN	2N5089 (Cont'd) BC549B 3 PHIN BCF33 3 APX PHIN MMBT5088 3 MOTA MMBT5089 3 MOTA SC239 3 MIKG THBC169 3 SPR THBC184 3 SPR THBC239 3 SPR 2N5090 2N3375 1 PHIN IT122 1 INL D40D4 3 GESY MP310 3 MPS 2N5091 2N5416 1 RCA DE397 3 DGE 2N5092 2N3439 1 RCA DE154 1 DGE DE396 3 DGE 2N5094 DE397 1 DGE 2N5095 DE396 1 DGE 2N5096 DE397 1 DGE 2N5102 2N5071 1 MOTA BLY93A 3 PHIN 2N5103 2N4416 1 INL DE459 1 DGE THJ5103 1 SPR THJ5103 1 SPR TP5103 1 SPR DE452 3 DGE THJ4416 3 SPR TMPF4416 3 SPR TP4416 3 SPR 2N5104 2N4416 1 MOTA 2N4416 1 INL SIX DE459 1 DGE THJ5104 1 SPR THJ5104 1 SPR TMPF5104 1 SPR TP5104 1 SPR 2N5347 3 MOTA DE452 3 DGE THJ4416 3 SPR TMPF4416 3 SPR TP4416 3 SPR 2N5105 2N4416 1 MOTA 2N4416 1 IFC INL SIX DE459 1 DGE THJ5105 1 SPR TMPF5105 1 SPR TP5105 1 SPR 2N5347 3 MOTA DE452 3 DGE THJ4416 3 SPR TMPF4416 3 SPR TP4416 3 SPR 2N5106 DE311 1 DGE 2N5108 DE311 1 DGE 2N5109 DE311 1 DGE 2N5943 3 MOTA 2N5110 2N5783 1 RCA DE129 1 DGE BSS44 3 SGSI D42C7 3 GESY SDT3552 3 SOD 2N5111 DE129 1 DGE 2N5112 D45C4 1 GESY 2N6109 3 RCA BD240 3 RCA ST45C4 3 STI 2N5114 2N3993 1 MOTA THJ5114 1 SPR TMPF5114 1 SPR TP5114 1 SPR 2N3386 3 SIX 2N3993 3 IFC 2N5014 3 SIX 2N5116 3 NSC SIX DE160 3 DGE PN4392-18 3 SIX THJ3993 3 SPR TP3993 3 SPR THJU304 3 SPR	2N5114 (Cont'd) TMPF3993 3 SPR TMPFU304 3 SPR TP3993 3 SPR TPU304 3 SPR 2N5115 2N3993 1 MOTA THJ5115 1 SPR TMPF5115 1 SPR TP5115 1 SPR 2N3386 3 SIX 2N3972 3 MOTA 2N3993 3 IFC INL 2N3994 3 MOTA 2N4860 3 SIX 2N4861 3 NSC SIX 2N5018 3 SIX 2N5116 3 NSC SIX 2N5145 3 NSC SIX 2N5461 3 MOTA DE160 3 DGE DE326 3 DGE PI086-18 3 NSC PN4392-18 3 SIX THJ3993 3 SPR TMPF3993 3 SPR TP3993 3 SPR 2N5116 2N3994 1 MOTA THJ5116 1 SPR TMPF5116 1 SPR TP5116 1 SPR 2N2609 3 MOTA 2N3382 3 SIX 2N3386 3 SIX 2N3993 3 MOTA 2N3994 3 IFC INL 2N5019 3 NSC SIX DE160 3 DGE THJ3993 3 SPR THJ3994 3 SPR THJU305 3 SPR TMPF3993 3 SPR TMPF3994 3 SPR TMPFU305 3 SPR TP3993 3 SPR TP3994 3 SPR TPU305 3 SPR 2N5117 2N5796 1 MOTA MP352-78 1 MPS DE82 3 DGE IT139 3 INL 2N5118 2N5796 1 MOTA MP352-78 1 MPS 3 DGE IT139 3 INL 2N5119 2N5796 1 MOTA MP351-78 1 MPS 3 DGE IT139 3 INL 2N5120 2N5796 1 MOTA IT131 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS 2N5121 2N5796 1 MOTA IT132 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS 2N5122 2N5796 1 MOTA IT132 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS 2N5123 2N5796 1 MOTA IT131 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS 2N5124 2N5796 1 MOTA IT132 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS 2N5125 (Cont'd) IT139 3 INL MP351 3 MPS 2N5126 2N918 1 THCS DE123AP 1 DGE BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR 2N5127 2N918 1 THCS DE123AP 1 DGE PN5127-18 1 NSC THC5127 1 SPR TP5127 1 SPR BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR 2N5128 2N2219 1 SGSI DE123AP 1 DGE PN5128-5 1 NSC THC5128 1 SPR DE128 3 DGE GES2219 3 GESY THC2219 3 SPR TN2219 3 NSC TP2219 3 SPR 2N5129 DE123AP 1 DGE PN5129-5 1 NSC THC5129 1 SPR 2N5130 2N918 1 THCS DE108 1 DGE PN5130-18 1 NSC THC5130 1 SPR BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR 2N5131 DE123AP 1 DGE PN5131-18 1 NSC THC5131 1 SPR TP5131 1 SPR 2N5132 BC109 1 SGSI DE123AP 1 DGE PN5132-18 1 NSC THC5132 1 SPR TP5132 1 SPR BCF32 3 PHIN THBC109 3 SPR 2N5133 DE123AP 1 DGE GES5133 1 GESY PN5133-18 1 NSC THC5133 1 SPR TP5133 1 SPR 2N5134 DE123AP 1 DGE PN5134-18 1 NSC 2N5135 BCY58 1 SGSI DE123AP 1 DGE PN5135-18 1 NSC THC5135 1 SPR BCF32 3 PHIN BCF33 3 PHIN 2N5136 BC119 1 SGSI DE123AP 1 DGE PN5136-18 1 NSC THC5136 1 SPR 2N697 3 RCA D40D2 3 GESY 2N5137 DE123AP 1 DGE PN5137-18 1 NSC THC5137 1 SPR TP5137 1 SPR 2N5138 BCY79 1 SGSI DE159 1 DGE PN5138-18 1 NSC THC5138 1 SPR TP5138 1 SPR BC850C 3 PHIN BC860A 3 PHIN BCF70 3 PHIN 2N5139 BC558 1 PHIN DE159 1 DGE PN5139-18 1 NSC THC5139 1 SPR	