

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
<b>2N5038</b> (Cont'd) DE327 1 DGE SDT7603 1 SOD SDT7609 1 SOD 2N3448 3 MOTA 2N6338 3 MOTA BUX11N 3 SGSI	<b>2N5053</b> (Cont'd) BY90 3 APX DE316 3 DGE <b>2N5054</b> 2N6304 1 MOTA DE161 1 DGE SD1300 1 THCS A490 3 APX BFY90 3 APX DE316 3 DGE <b>2N5055</b> DE159 1 DGE <b>2N5056</b> 2N4209 1 MOTA DE159 1 DGE PN3640 3 NSC <b>2N5057</b> 2N4209 1 MOTA DE159 3 DGE PN3640 3 NSC <b>2N5058</b> 2N3439 1 RCA D44T2 1 GESY DE154 1 DGE THC5058 1 SPR TP5058 1 SPR DE396 3 DGE <b>2N5059</b> 2N3440 1 RCA D44T4 1 GESY DE154 1 DGE THC5059 1 SPR TP5059 1 SPR BD115 3 PHIN BFN18 3 SIEG BFN26 3 SIEG D44T2 3 GESY DE396 3 DGE TN3440 3 NSC <b>2N5066</b> DE123A 1 DGE <b>2N5067</b> 2N5758 1 MOTA BDX91 1 PHIN D44VM4 1 GESY DE130 1 DGE 2N3442 3 RCA 2N4914 3 RCA 2N6262 3 RCA BDW21A 3 SGSI BDW51C 3 SGSI DE385 3 DGE <b>2N5068</b> 2N5758 1 MOTA BDX91 1 PHIN D44VM7 1 GESY DE130 1 DGE 2N3442 3 RCA 2N4914 3 RCA 2N6262 3 RCA BDW21A 3 SGSI BDW51C 3 SGSI DE385 3 DGE <b>2N5069</b> 2N5758 1 MOTA BDX93 1 PHIN D44VM10 1 GESY DE130 1 DGE THC5069 1 SPR 2N3442 3 RCA 2N4914 3 RCA 2N6262 3 RCA BDW21B 3 SGSI BDW51C 3 SGSI DE385 3 DGE <b>2N5070</b> BLX13 1 PHIN MRF426A 3 MOTA <b>2N5071</b> BLY93A 1 PHIN 2N3927 3 MOTA 2N5477 3 GSE 2N5643 3 THCS MRF314A 3 MOTA <b>2N5072</b> BLY90 1 PHIN 2N6084 3 THCS MRF240 3 MOTA <b>2N5073</b> DE154 1 DGE <b>2N5074</b> DE95 1 DGE <b>2N5075</b> DE95 1 DGE <b>2N5076</b> DE95 1 DGE <b>2N5077</b> 2N4416 1 IFC 2N5397 1 INL DE452 1 DGE THJ5078 1 SPR TMPF5078 1 SPR TP5078 1 SPR	<b>2N5078</b> (Cont'd) 2N5485 3 MOTA 2N5486 3 INL THJ4416 3 SPR THJ5397 3 SPR TMPF4416 3 SPR TMPF5397 3 SPR TP4416 3 SPR TP5397 3 SPR U309 3 MOTA U310 3 SIX <b>2N5079</b> D40D2 1 GESY <b>2N5080</b> D40D2 1 GESY DE123A 1 DGE <b>2N5081</b> DE123A 1 DGE <b>2N5082</b> DE123A 1 DGE <b>2N5083</b> 2N5347 1 MOTA D44VM10 3 GESY <b>2N5084</b> 2N5347 1 MOTA D44VM10 3 GESY <b>2N5085</b> 2N5347 1 MOTA D44VM10 3 GESY <b>2N5086</b> BC557 1 PHIN BCX71C 1 SIEG BCX71D 1 SIEG BCY79 1 SGSI DE159 1 DGE PN200 1 NSC THC5086 1 SPR TMPT5086 1 SPR 2N2907A 3 PHIN BC478 3 SGSI BC850C 3 PHIN BC860A 3 PHIN BC875A 3 PHIN BCF29 3 APX BCF70 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN BCY70 3 PHIN BCY71 3 PHIN MMBT5086 3 MOTA THC557 3 SPR THC2604 3 SPR THC2605 3 SPR THC3962 3 SPR <b>2N5086-18</b> DE159 3 DGE THC4965 3 SPR <b>2N5087</b> BCX71C 1 SIEG BCX71D 1 SIEG BCY79 1 SGSI DE159 1 DGE PN200 1 NSC THC5087 1 SPR TMPT5087 1 SPR BC177 3 SGSI BC178 3 SGSI BC179 3 SGSI BC214L 3 SPR BC559 3 PHIN BC850C 3 PHIN BC860A 3 PHIN BCF30 3 APX BCF70 3 PHIN BCY71 3 PHIN MMBT5087 3 MOTA THC214 3 SPR THC3964 3 SPR THC3965 3 SPR <b>2N5088</b> BC547A 1 PHIN BCW60D 1 SIEG BCY59 1 SGSI DE123AP 1 DGE PN200 1 NSC THC5088 1 SPR TMPT5088 1 SPR BCF32 3 APX BCW71 3 PHIN MMBT5088 3 MOTA THBC547A 3 SPR <b>2N5089</b> BC549C 1 PHIN BCW60D 1 SIEG BCY59 1 SGSI DE123AP 1 DGE THC5089 1 SPR TMPT5089 1 SPR BC107 3 SGSI BC109 3 SGSI BC184L 3 SPR BC549 3 PHIN	<b>2N5089</b> (Cont'd) BC549B 3 PHIN BCF33 3 APX PHIN MMBT5088 3 MOTA MMBT5089 3 MOTA SC239 3 MIKG THBC169 3 SPR THBC184 3 SPR THBC239 3 SPR <b>2N5090</b> 2N3375 1 PHIN IT122 1 INL D40D4 3 GESY MP310 3 MPS <b>2N5091</b> 2N5416 1 RCA DE397 3 DGE <b>2N5092</b> 2N3439 1 RCA DE154 1 DGE DE396 3 DGE <b>2N5094</b> DE397 1 DGE <b>2N5095</b> DE396 1 DGE <b>2N5096</b> DE397 1 DGE <b>2N5102</b> 2N5071 1 MOTA BLY93A 3 PHIN <b>2N5103</b> 2N4416 1 INL DE459 1 DGE THJ5103 1 SPR THJ5104 1 SPR TMPT5103 1 SPR TP5103 1 SPR DE452 3 DGE THJ4416 3 SPR TMPF4416 3 SPR TP4416 3 SPR <b>2N5104</b> 2N4116 1 MOTA 2N4416 1 INL SIX DE459 1 DGE THJ5104 1 SPR THJ5105 1 SPR TMPT5104 1 SPR TP5104 1 SPR 2N5347 3 MOTA DE452 3 DGE THJ4416 3 SPR TMPF4416 3 SPR TP4416 3 SPR <b>2N5105</b> 2N4116 1 MOTA 2N4416 1 IFC INL SIX DE459 1 DGE THJ5105 1 SPR TMPT5105 1 SPR TP5105 1 SPR 2N5347 3 MOTA DE452 3 DGE THJ4416 3 SPR TMPF4416 3 SPR TP4416 3 SPR <b>2N5106</b> DE311 1 DGE <b>2N5108</b> DE311 1 DGE <b>2N5109</b> DE311 1 DGE 2N5943 3 MOTA <b>2N5110</b> 2N5783 1 RCA DE129 1 DGE BSS44 3 SGSI D42C7 3 GESY SDT3552 3 SOD <b>2N5111</b> DE129 1 DGE <b>2N5112</b> D45C4 1 GESY 2N6109 3 RCA BD240 3 RCA ST45C4 3 STI <b>2N5114</b> 2N3993 1 MOTA THJ5114 1 SPR TMPF5114 1 SPR TP5114 1 SPR 2N3386 3 SIX 2N3993 3 IFC 2N5014 3 SIX 2N5116 3 NSC SIX DE160 3 DGE PN4392-18 3 SIX THJ3993 3 SPR THJ3993 3 SPR TP3993 3 SPR	<b>2N5114</b> (Cont'd) TMPF3993 3 SPR TMPFU304 3 SPR TP3993 3 SPR TPU304 3 SPR <b>2N5115</b> 2N3993 1 MOTA THJ5115 1 SPR TMPF5115 1 SPR TP5115 1 SPR 2N3386 3 SIX 2N3972 3 MOTA 2N3993 3 IFC INL 2N3994 3 MOTA 2N4860 3 SIX 2N4861 3 NSC SIX 2N5018 3 SIX 2N5116 3 NSC SIX 2N5145 3 NSC SIX 2N5461 3 MOTA DE160 3 DGE DE326 3 DGE PI086-18 3 NSC PN4392-18 3 SIX THJ3993 3 SPR TMPF3993 3 SPR TP3993 3 SPR <b>2N5116</b> 2N3994 1 MOTA THJ5116 1 SPR TMPF5116 1 SPR TP5116 1 SPR 2N2609 3 MOTA 2N3382 3 SIX 2N3386 3 SIX 2N3993 3 MOTA 2N3994 3 IFC INL 2N5019 3 NSC SIX DE160 3 DGE THJ3993 3 SPR THJ3994 3 SPR THJU305 3 SPR TMPF3993 3 SPR TMPF3994 3 SPR TMPFU305 3 SPR TP3993 3 SPR TP3994 3 SPR TPU305 3 SPR <b>2N5117</b> 2N5796 1 MOTA MP352-78 1 MPS DE82 3 DGE IT139 3 INL <b>2N5118</b> 2N5796 1 MOTA MP352-78 1 MPS 3 DGE IT139 3 INL <b>2N5119</b> 2N5796 1 MOTA MP351-78 1 MPS 3 DGE IT139 3 INL <b>2N5120</b> 2N5796 1 MOTA IT131 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS <b>2N5123</b> 2N5796 1 MOTA IT131 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS <b>2N5124</b> 2N5796 1 MOTA IT132 1 INL DE82 3 DGE IT139 3 INL MP351 3 MPS <b>2N5125</b> (Cont'd) IT139 3 INL MP351 3 MPS <b>2N5126</b> 2N918 1 THCS DE123AP 1 DGE BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR <b>2N5127</b> 2N918 1 THCS DE123AP 1 DGE PN5127-18 1 NSC THC5127 1 SPR TP5127 1 SPR BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR <b>2N5128</b> 2N2219 1 SGSI DE123AP 1 DGE PN5128-5 1 NSC THC5128 1 SPR DE128 3 DGE GES2219 3 GESY THC2219 3 SPR TN2219 3 NSC TP2219 3 SPR <b>2N5129</b> DE123AP 1 DGE PN5129-5 1 NSC THC5129 1 SPR <b>2N5130</b> 2N918 1 THCS DE108 1 DGE PN5130-18 1 NSC THC5130 1 SPR BF799 3 SIEG DE161 3 DGE PN918 3 NSC THC918 3 SPR TMPT918 3 SPR TP918 3 SPR <b>2N5131</b> DE123AP 1 DGE PN5131-18 1 NSC THC5131 1 SPR TP5131 1 SPR <b>2N5132</b> BC109 1 SGSI DE123AP 1 DGE PN5132-18 1 NSC THC5132 1 SPR TP5132 1 SPR BCF32 3 PHIN THBC109 3 SPR <b>2N5133</b> DE123AP 1 DGE GES5133 1 GESY PN5133-18 1 NSC THC5133 1 SPR TP5133 1 SPR <b>2N5134</b> DE123AP 1 DGE PN5134-18 1 NSC <b>2N5135</b> BCY58 1 SGSI DE123AP 1 DGE PN5135-18 1 NSC THC5135 1 SPR BCF32 3 PHIN BCF33 3 PHIN <b>2N5136</b> BC119 1 SGSI DE123AP 1 DGE PN5136-18 1 NSC THC5136 1 SPR 2N697 3 RCA D40D2 3 GESY <b>2N5137</b> DE123AP 1 DGE PN5137-18 1 NSC THC5137 1 SPR TP5137 1 SPR <b>2N5138</b> BCY79 1 SGSI DE159 1 DGE PN5138-18 1 NSC THC5138 1 SPR TP5138 1 SPR BC850C 3 PHIN BC860A 3 PHIN BCF70 3 PHIN <b>2N5139</b> BC558 1 PHIN DE159 1 DGE PN5139-18 1 NSC THC5139 1 SPR	