

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
2SC1507 TIP48 1 MOTA SGSI BUX84 3 PHIN ST48 3 STI	2SC1586 (Cont'd) BDY45 3 ALGG D64V53 3 GESY DE286 3 DGE SVT7553 3 TRWS	2SC1623L6 MMBC1623L6 1 MOTA TMPT1623L6 3	2SC1728 MPSU07 1 MOTA	2SC1826 (Cont'd) BD243B 3 RCA BDX77 3 PHIN D44VM10 3 GESY STD5903 3 SOD	2SC1884 2N6301 1 MOTA D44E3 3 GESY DE274 3 DGE
2SC1514 D40V3 1 GESY MJE3439 1 MOTA SGSI D44T3 3 GESY	2SC1589 MRF227 1 MOTA MRF260 1 MOTA SD1444 3 THCS	2SC1623L7 TMPT1623L7 1 MOTA	2SC1729 MRF226 1 MOTA MRF2628 1 MOTA SD1143 3 THCS	2SC1827 TIP41C 1 APX BD243C 1 MOTA STD5904 3 RCA SOD 3	2SC1891 BU204 1 MOTA BU208 1 SGSI 2SC1875 3 NECE SU160 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1516 BD437 1 SGSI D42C3 1 GESY MJE3300 1 MOTA 2N6288 3 RCA BD675 3 APX PHIN D44D1 3 GESY MDS26 3 MOTA	2SC1590 MRF260 1 MOTA MRF262 1 MOTA	2SC1625 TIP29C 1 SGSI BD239C 3 RCA	2SC1733 NE73416 1 NECE	2SC1829 BU931R 1 SGSI MJ3041 1 MOTA BU920 3 SGSI BUX37 3 ALGG	2SC1892 BU205 1 MOTA BU208 1 SGSI 2SC1875 3 NECE 2SD818 3 TOSJ SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1517 2N4922 1 MOTA BD439 1 SGSI BD137 3 ALGG PHIN D44C8 3 GESY DE184 3 DGE	2SC1592 MRF587 1 MOTA NE41620 1 NECE BFR94 3 APX	2SC1626 TIP29B 1 SGSI BD239B 3 RCA D44C10 3 GESY	2SC1749 MJE340 1 MOTA SGSI BD127 3 ALGG BD128 3 ALGG BD232 3 PHIN BUX99 3 APX D44T6 3 GESY	2SC1830 2N6578 1 MOTA BDX67C 1 APX BDX65C 3 PHIN DE249 3 DGE	2SC1893 BU208 1 SGSI BUY89 1 APX MJ12003 1 MOTA 2SC1875 3 NECE ST12003 3 STI SU160 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1517A BD441 1 SGSI D42C11 1 GESY 2N6292 3 RCA	2SC1594 MRF587 1 MOTA NE64320 1 NECE BFR94 3 APX	2SC1628 MPSU04 1 MOTA GESU04 3 GESY	2SC1755 MJE2360T 1 MOTA	2SC1831 2N6056 1 MOTA SGSI BDX63A 3 PHIN DE243 3 DGE PMD12K80 3 LAM	2SC1894 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1519 2N6557 1 MOTA DE171 3 DGE	2SC1598 MRF587 1 MOTA NE64320 1 NECE BFR94 3 APX	2SC1629 MJ1001 1 MOTA BDX63A 3 PHIN D44E3 3 GESY LMJ1001 3 LAM PMD12K80 3 LAM RCA1001 3 RCA	2SC1756 MJE2360T 1 MOTA	2SC1832 BDX63A 3 PHIN DE243 3 DGE PMD12K80 3 LAM	2SC1895 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1520 2N6557 1 MOTA DE171 3 DGE	2SC1600 MRF586 1 MOTA NE57510 1 NECE	2SC1630 MPSU04 1 MOTA GESU04 3 GESY	2SC1757 MJE2360T 1 MOTA	2SC1833 BU932R 1 SGSI BUX37 1 ALGG MJ10009 1 MOTA 2SD683 3 TOSJ BU931 3 SGSI BU931R 3 SGSI BUX37A 3 RCA BUX90 3 VALG GE062 3 GESY GE10009 3 GESY PTC10009 3 PTC SDM6000 3 SOD ST10009 3 STI	2SC1896 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1521 2N6557 1 MOTA DE171 3 DGE	2SC1603 2N5944 1 MOTA MRF752 1 MOTA	2SC1642 MRF587 1 MOTA NE57520 1 NECE BFR94 3 APX	2SC1761 MPSU01 1 MOTA GESU01 3 GESY	2SC1834 BU932R 1 SGSI BUX37 1 ALGG MJ10009 1 MOTA 2SD683 3 TOSJ BU931 3 SGSI BU931R 3 SGSI BUX37A 3 RCA BUX90 3 VALG GE062 3 GESY GE10009 3 GESY PTC10009 3 PTC SDM6000 3 SOD ST10009 3 STI	2SC1897 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1560 2N6603 1 MOTA MRF572 1 MOTA NE02103 1 NECE A501 3 APX BFR94 3 APX	2SC1604 MRF628 1 MOTA MRF750 1 MOTA MRF559 3 MOTA SD1080-2 3 THCS	2SC1644 MRF587 1 MOTA NE57520 1 NECE BFR94 3 APX	2SC1763 MRF464 1 MOTA	2SC1835 BU932R 1 SGSI BUX37 1 ALGG MJ10009 1 MOTA 2SD683 3 TOSJ BU931 3 SGSI BU931R 3 SGSI BUX37A 3 RCA BUX90 3 VALG GE062 3 GESY GE10009 3 GESY PTC10009 3 PTC SDM6000 3 SOD ST10009 3 STI	2SC1898 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1565 MJE340 1 SGSI BD127 3 ALGG BD128 3 ALGG BD232 3 PHIN BUX99 3 APX D44T6 3 GESY	2SC1605A MRF226 1 MOTA MRF2628 1 MOTA SD1143 3 THCS	2SC1645 MPSU04 1 MOTA GESU04 3 GESY	2SC1764 MRF464 1 MOTA	2SC1836 BU932R 1 SGSI BUX37 1 ALGG MJ10009 1 MOTA 2SD683 3 TOSJ BU931 3 SGSI BU931R 3 SGSI BUX37A 3 RCA BUX90 3 VALG GE062 3 GESY GE10009 3 GESY PTC10009 3 PTC SDM6000 3 SOD ST10009 3 STI	2SC1899 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1576 BUS23C 1 APX BUW34 1 SGSI BUX16 1 RCA MJ13091 1 MOTA BUW24 3 SGSI BUX32 3 RCA BUX82 3 PHIN	2SC1606 2N6080 1 MOTA MRF327 1 MOTA BLX67 3 PHIN DE348 3 DGE SD1468 3 THCS	2SC1646 MMBC1654N5 1 MOTA TMPT1654N5 3	2SC1765 MRF464 1 MOTA	2SC1837 BD135 3 ALGG D42C5 3 GESY	2SC1900 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1577 BUS23C 1 APX BUW34 1 SGSI MJ13091 1 MOTA BUX32 3 RCA	2SC1609 2N6340 1 MOTA BUX11N 3 SGSI DE327 3 DGE	2SC1647 MMBC1654N6 1 MOTA TMPT1654N6 3	2SC1766 MRF464 1 MOTA	2SC1838 BD137 3 ALGG D42C8 3 GESY	2SC1901 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1578 BUW35 1 SGSI MJ10014 1 MOTA BUX32 3 RCA ST10014 3 STI	2SC1610 2N6341 1 MOTA BUX11N 3 SGSI DE327 3 DGE TIP516 3 TII	2SC1648 MMBC1654N7 1 MOTA TMPT1654N7 3	2SC1767 MRF464 1 MOTA	2SC1839 BD137 3 ALGG D42C8 3 GESY	2SC1902 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1579 BUW44 1 SGSI MJ10013 1 MOTA 2N6678 3 RCA ST10013 3 STI	2SC1611 MRF326 1 SGSI BUS21 1 APX MJ411 1 MOTA BU526 3 ALGG D44TE3 3 GESY IR411 3 INR RCA411 3 RCA	2SC1649 MMBC1654N8 1 MOTA TMPT1654N8 3	2SC1768 MRF464 1 MOTA	2SC1840 BD137 3 ALGG D42C8 3 GESY	2SC1903 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1580 BUW45 1 SGSI MJ10014 1 MOTA ST10014 3 STI	2SC1612 2N6342 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA 2N6472 3 RCA BDW51C 3 SGSI DE385 3 DGE	2SC1650 MMBC1654N9 1 MOTA TMPT1654N9 3	2SC1769 MRF464 1 MOTA	2SC1841 BD137 3 ALGG D42C8 3 GESY	2SC1904 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1584 2N6249 1 MOTA BUX41 1 SGSI 2N6674 3 PTC D64V53 3 GESY DE286 3 DGE SDT7605 3 SOD SDT7610 3 SOD SDT7611 3 SOD SDT7612 3 SOD SVT7563 3 TRWS	2SC1613 2N6343 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA 2N6472 3 RCA BDW51C 3 SGSI DE385 3 DGE	2SC1651 MMBC1654N10 1 MOTA TMPT1654N10 3	2SC1770 MRF464 1 MOTA	2SC1842 BD137 3 ALGG D42C8 3 GESY	2SC1905 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1585 2N6249 1 MOTA BUX41 1 SGSI 2N6674 3 PTC D64V53 3 GESY DE286 3 DGE SDT7605 3 SOD SDT7610 3 SOD SDT7611 3 SOD SDT7612 3 SOD SVT7563 3 TRWS	2SC1614 2N6344 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA 2N6472 3 RCA BDW51C 3 SGSI DE385 3 DGE	2SC1652 MMBC1654N11 1 MOTA TMPT1654N11 3	2SC1771 MRF464 1 MOTA	2SC1843 BD137 3 ALGG D42C8 3 GESY	2SC1906 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII
2SC1586 2N6250 1 MOTA BUX42 1 SGSI	2SC1615 2N6345 1 MOTA BDW51C 1 SGSI 2N3442 3 RCA 2N6262 3 RCA 2N6472 3 RCA BDW51C 3 SGSI DE385 3 DGE	2SC1653 MMBC1654N12 1 MOTA TMPT1654N12 3	2SC1772 MRF464 1 MOTA	2SC1844 BD137 3 ALGG D42C8 3 GESY	2SC1907 SU160 3 MIKG SU161 3 MIKG TIP550 3 TII TIP553 3 TII